Q-339

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

QVM BULLETIN: Q-339 DATE: 11 / AUG / 2021

2021 TRANSIT, E-SERIES, MOTORHOME AND UTILITY CHASSIS FUEL TANK PRESSURE TRANSDUCER CONTAMINATION

REVISION	UPDATE	REVISION DATE
Q-339	INITIAL RELEASE	11/AUGUST/2021

MODEL(S) AFFECTED:

2021 MY Transit, E-Series, Motorhome and Utility chassis.

ISSUE / DESCRIPTION:

During vehicle upfit it has been found that the Fuel Tank Pressure Transducer is being contaminated with overspray and dirt. It is recommended that the area identified in the diagrams below be covered to protect the transducer from overspray and other contaminates during vehicle upfit.

Fuel Tank Pressure Transducer on Transit vehicles

Fuel Tank Pressure Transducer.



Area to protect during vehicle upfit. Transit



Motorhome chassis Fuel Tank Pressure Transducer



Motorhome Chassis, 80 Gallon fuel tank



Utility Chassis Fuel Pump Pressure Transducer location



Utility chassis 40 Gallon fuel tank



E-Series fuel Tank Pressure Transducer location



E-Series 40 Gallon fuel Tank **E-Series 55 Gallon fuel Tank**





Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the Ford Body Builders Advisory Service as shown in the header of this bulletin.